

RSH-HS03 ZigBee Smart Temperature

RSH-HS03 ZigBee Smart Temperature and Humidity Sensor

- High precision
- Real-time monitoring and recording
- LCD screen display
- Scene linkage
- Temperature Unit Switch



Model	RSH-HS03
Power Mode	3V AAA*2 battery
Rated Voltage	3V
Material	PC
Operating Temperature	-10-50°C
Working Humidity	10%-90%RH